Owner Name and Address: Horizon Resources 209 Washington Ave Williston ND 58801 Phone: (701) 572-2171

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4203363	Horizon Resources Fairview Store	605 S Ellery Ave	Fairview	59221	(406) 742-5273

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
7 / 07 Currently In Use	3722	12/1/1998 07 / No	Gasoline 7,800	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
8 / 08 Currently In Use	3723	12/1/1998 07 / No	Gasoline 4,200	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B DEF . H . J . K L	Yes Yes Yes Yes
9 / 09 Currently In Use	3724	12/1/1998 07 / No	Diesel 5,500	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
10 / 10 Currently In Use	3725	12/1/1998 07 / No	Diesel 4,500	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 15

Owner Name and Address: Mini Mart Inc 442 Keeler Pkwy Pueblo CO 81001 Phone: (719) 948-3071

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4203914	Mini Mart 714	516 S Ellery Ave	Fairview	59221	(406) 747-5024

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 04 Currently in Use	1646	8/1/1994 11 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
2 / 05 Currently in Use	1647	8/1/1994 11 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging C Invent	tory Control E Vapor Monit	toring G Interstit, Dbl-Wall Monitor	I SIR	K Deferred	
	,	9		L Not Listed	

Report Generation Date: 7/3/2006 Page 2 of 15

Owner Name and Address: Nortana Grain Co PO Box 177 Lambert MT 59243 Phone: (406) 774-3331

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4200317	Nortana Grain Co	100 1st Ave SW	Lambert	59243	(406) 774-3331

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	1754	11/1/1989 16 / No	Gasoline 500	STI-P3 Excavation Liner	Galvanized Steel Cathodically Protected	U.S. Suction	ABCDEFG#1JKL B DEFGH1•KL	Yes Yes Yes Yes
4 / 04 Currently in Use	1755	11/1/1989 16 / No	Gasoline 500	STI-P3 Excavation Liner	Galvanized Steel Cathodically Protected	U.S. Suction	ABCDEFGB1JKL B DEFGH1•KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 15

Owner Name and Address: Gregory Cross PO Box 1388 Glendive MT 59330 Phone: (406) 252-5519

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	7
4203815	Valley Fuel Supply	MT Highway 16	Savage	59262	(406) 776-2354	_

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently In Use	780	8/25/1998 07 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEF⊕HIJK L ● ●EFGHIJK L	Yes Yes Yes Yes
4 / 04 Currently In Use	781	8/1/1998 07 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEF⊕HJJK L ● ● E F G HJJKL	Yes Yes Yes Yes
5 / 05 Currently In Use	782	8/1/1998 07 / No	Diesel 3,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEF®HIJKL • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 15

Owner Name and Address: Lower Yellowstone Rural Electric PO Box 1047 Sidney MT 59270 Phone: (406) 488-1602

Association Inc

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4200001	Lower Yellowstone Rural Electric Associa	MT Highway 16 NW	Sidney	59270	(406) 488-1602

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently in Use	1558	10/1/1993 12 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF.H.J.K.L B.DEF.G.H.J.K.L	Yes Yes Yes Yes
6 / 06 Currently in Use	1559	10/1/1993 12 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	(ABCDEF.H)JKL B DEFGH)•KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 15

Owner Name and Address: Sweley Oil Inc 1051 10th Ave SE Sidney MT 59270 Phone: (406) 443-2508

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
4200183	Sweley Oil Inc Bulk Plant	3rd St SW & 10th Ave SW	 Sidney	59270	(406) 482-2508	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / S4 Currently In Use	2076	6/16/1998 08 / Ye	Diesel 17,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJEL B DEFOHIJEL	Yes Yes Yes Yes
5 / S5 Currently In Use	2077	6/16/1998 08 / Ye	Gasoline 17,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJEL B DEFOHIJEL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 15

Owner Name and Address: Gregory Cross PO Box 1388 Glendive MT 59330 Phone: (406) 252-5519

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
4202184	Sidney Cardtrol	901 3rd St NE	Sidney	59270	(406) 482-4376	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	776	4/17/1982 24 / No	Diesel 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	\(\begin{align*} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Yes Yes Yes Yes
2 / 02 Currently in Use	777	4/17/1982 24 / No	Diesel 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	(ABCO • F G H () () () ()	Yes Yes Yes Yes
3 / 03 Currently in Use	778	4/17/1982 24 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	ABCOOFGHIJKU O OFGHIJKU	Yes Yes Yes Yes
4 / 04 Currently in Use	779	4/17/1982 24 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	ABCOOFGHIJKL O OFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 15

Owner Name and Address: Thogersen Oil Inc 625 S Central Ave Sidney MT 59270 Phone: (406) 482-2402

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4203224	Thogersen Oil Inc	625 S Central Ave	Sidney	59270	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
10 / 12 Currently in Use	2112	7/11/1991 14 / No	Gasoline 8,000	Composite (Steel w/ FRP) Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	8 DEF 0 H 1 J K L	Yes Yes Yes Yes
11 / 13 Currently in Use	2113	7/11/1991 14 / No	Gasoline 8,000	Composite (Steel w/ FRP) Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	B DEF H J K L	Yes Yes Yes Yes
12 / 11 Currently in Use	2111	7/11/1991 14 / No	Diesel 8,000	Composite (Steel w/ FRP) Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	ABCDEF.H.I.J.K.L B.DEF.G.H.I.O.K.L	Yes Yes Yes Yes
13 / 10 Currently in Use	2110	7/11/1991 14 / No	Diesel 4,000	Composite (Steel w/ FRP) Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	ABCDEF.H.I.J.K.L. B.DEF.G.H.I.O.K.L.	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 15

Owner Name and Address: Cenex Harvest States 1281 S Central Ave Sidney MT 59270 Phone: (406) 433-1401

Sys Fac I	Location Name	Location Street Address	Location City	Zip	T	Location Phone	
4203364	Cenex Supply & Marketing Sidney	1281 S Central Ave	 Sidney	59270		(406) 482-1401	-

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 04	605 6/25/1981	Gasoline	STI-P3	Flexible Plastic	Pressurized	ABC•EFGH1JKL	Yes
Currently in Use	25 / No	15,000	None	Double-Walled		B DEF•H1JKL	Yes Yes Yes
2 / 05 Currently In Use	4046 6/25/1981 25 / No	Diesel 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B DEF@HJJ&L	Yes Yes Yes Yes
4 / 01	602 6/25/1981	Gasoline	STI-P3	Flexible Plastic	Pressurized	ABCOEFGHJ&L	Yes
Currently in Use	25 / No	20,000	None	Double-Walled		B DEFOHJ&L	Yes Yes Yes
5 / 02	603 6/25/1981	Gasoline	STI-P3	Flexible Plastic	Pressurized	ABC • E F G H J & L	Yes
Currently in Use	25 / No	20,000	None	Double-Walled		B D E F • H J & L	Yes Yes Yes
6 / 03	604 6/25/1981	Diesel	STI-P3	Flexible Plastic	Pressurized	ABC•EFGH1JKL	Yes
Currently in Use	25 / No	20,000	None	Double-Walled		B DEF•H1JKL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 15

Owner Name and Address: Sidney Airport Service PO Box 355 Sidney MT 59270 Phone: (406) 488-4031

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4204444	Sidney Airport Service	355 Airport Road	Sidney	59270	(406) 482-4031

TankID/Alt TankID Status	Tag Insta		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently In Use	3969 4/1/199	09 Other / No 12,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	B DEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 10 of 15

Owner Name and Address: Mini Mart Inc 442 Keeler Pkwy Pueblo CO 81001 Phone: (719) 948-3071

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4205084	Mini Mart 712	706 S Central Ave	Sidney	59270	(406) 482-5647

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4586	4/24/1976 30 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	ABCOEFGHIJKL O DEFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently In Use	4587	4/24/1976 30 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	(ABCOEFGH) () (KL) (O) (D) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B	Yes Yes Yes Yes
3 / 03 Currently in Use	4588	4/24/1976 30 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	(ABCOEFGHIJKU (DEFGHIJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 15

Owner Name and Address: Sidney Health Center 216 14th Ave SW Sidney MT 59270 Phone: (406) 482-2120

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4206159	Sidney Health Center	216 14th Ave SW	Sidney	59270	(406) 482-2120

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently In Use	700	9/1/1997 08 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	(ABCDEF●H)() (B DEF●H)()	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 15

Owner Name and Address: Wyoming Alaska Company Inc PO Box 667 Centerville UT 84014 Phone: (801) 292-2207

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4207789	Trailside General Store Sidney	1055 S Central Ave	Sidney	59270	(406) 482-3418

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3882	4/22/1976 30 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	A • • D E F G H I J K L • • E F G H I J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	3883	4/22/1976 30 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized		Yes Yes Yes Yes
3 / 03 Currently in Use	3884	4/22/1976 30 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	(A	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 15

Owner Name and Address: Superpumper Inc PO Box 1847 Minot ND 58702 Phone: (701) 852-0061

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
4209718	Superpumper Inc 23	902 S Central Ave	Sidney	59270	(406) 482-3616

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	3072	7/1/1992 14 / No	Gasoline 15,000	STI-P3 None	No Piping None	Pressurized	ABCDEFGHOJKL B DEFGHOJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	3073	7/1/1992 14 / No	Gasoline 12,000	STI-P3 None	No Piping None	Pressurized	ABC • E F G H • J K L B D E F G H J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 15

Owner Name and Address: Millers Corner LLC HC 89 Box 5043 Sidney MT 59270 Phone: (406) 433-4041

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614071	Millers Corner LLC	MT Highway 16 & 22nd Ave NW	Sidney	59270	(406) 433-4041

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4797	2/6/2003 03 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently In Use	4798	2/6/2003 03 / No	Diesel 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes
3 / 03 Currently In Use	4799	2/6/2003 03 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 15 of 15